

MATCHING MOTORS TO AMPLIFIERS

GATHER THESE PARAMETERS (NOT ALL ARE USED IN ALL SYSTEMS):

Motor	Amplifier	Power Supply
Type (brush, brushless servo, stepper)	Type (brush, brushless servo, stepper)	Bus Voltage out
# of Phases	Commutation	Line Voltage In
I _{peak} (peak current)	Bus Voltage	Regen Capacity (if any, how much?)
I _{rms} (continuous current)	Line Voltage In (AC or DC)	Capacitance (Voltage Ripple)
T _{rms} (at what temp? 25C, 40C?)	Type of current control (PWM, Linear)	I _{peak}
V _{peak} (max bus voltage)	I _{rms}	I _{rms}
ω _m (peak motor speed)	I _{peak}	Type (Linear, switching)
J _m (motor inertia)	Minimum acceptable motor inductance	
T _p (peak torque)	PWM switching frequency (higher needed in tiny motors)	
K _T (torque constant)		
K _e (back emf constant)		
commutation type		
Inductance		
Resistance		
Static Friction		

BASED ON THE ABOVE PARAMETERS, FOLLOW THESE STEPS IN ROUGH ORDER:

1. Determined T_p and ω required.
2. What line voltage is available?
3. Choose motor w/T_p, ω_m
4. Use k_T to find how much I_{peak} is needed for T_p.
5. Use k_e to find how much V_{peak} is needed to go ω. $K_e(V/krpm)=0.740KT(oz-in/amp)$ Or $= V_{rms}/\omega_{rms}$
6. Choose type of amp to match motor (also consider commutation type: sine vs trapezoidal)
7. Choose the amplifier that has sufficient I_{peak} and I_{cont}, V_{bus}
8. Check line voltage of the amp, see if an external power supply is needed.
9. If Amp takes AC input, skip to step 12.
10. Pick P.S. compatible with line, DC voltage, & current requirements
11. Is a switching power supply needed? If not, confirm that max voltage does not exceed amp max voltage.
12. If match between power supply, amp, and motor is difficult, consider change in motor winding.
13. Check regen in amp and/or power supply
14. Confirm that the min. inductance of the amp is less than the motor.